

## Failure of Scubapro G2C Compass

Fails to indicate magnetic North. Compared to Scubapro FS2 compass, Shearwater Petrel, and Apple iPhone. All indicate correct direction except for the Scubapro G2C.



Turning 90 degrees. Even with the bad heading, turning 90 degrees does not give a 90 degree change of the incorrect heading. Correct heading shown by Scubapro FS2, Shearwater Petrel and Apple iPhone was 90 degrees. I would have expected the G2C to at least indicate 49 degrees which would be 90 degrees from the incorrect 319 heading. 90 degree turn is only showing a 53 degree change on the G2C.

