

Pacific Housing Repair

820 Park Row #600
Salinas, CA 93901

Estimate

Date	Estimate No.
1/22/2019	1499

Name/Address

Scott Newland
Indian Harbour, FL 32937

Item	Description	Qty	Rate	Total
Estimate.ScotNewl	Sea & Sea YS-110 #052105615, w/ battery cap, sync cap, diffuser, w/o fix bolt. Strobe has damaged transformer on main circuit assembly. // Estimate: Strobe Minor Service + repair of main circuit assembly. Customer is interested in refurbished YS-110.		0.00	0.00
Strobe Service-Minor	Labor: Installation of main-body and user o-rings, function and pressure tests	1	91.00	91.00
Strobe Parts Kit	Parts-Minor Service	1	20.00	20.00T
Labor	Hourly labor rate; to repair Main Circuit Assembly.	1	85.00	85.00
Misc Electrical	Parts; including transformer.	3	10.00	30.00T
YS-110 Strobe, Refurb	Sale of refurbished unit; w/ diffuser & fix bolt.	1	295.00	295.00T
Shipping Estimate	Estimated shipping handling & insurance, based upon ground shipping rates		28.85	28.85
	Out-of-state sale, exempt from sales tax		0.00%	0.00
Total				\$549.85

Phone #	E-mail
831-751-3885	service@PacificHousingRepair....