

# Aqua Lung America

## ***TECHNICAL BULLETIN***

June 15, 2011  
No. 34

**SUBJECT:** Change in torque specification for the heat exchanger on Apeks XTX, ATX and TX second stages.

**PRODUCTS AFFECTED:** The regulators in question are all models of Apeks XTX, ATX and TX second stages.

This bulletin is being issued to pass on information with regard to assisting the servicing of the Apeks regulator range.

To avoid causing damage to the 2nd stage case, we have decreased the torque specification for the heat exchanger from 45 in-lbs (5Nm) to 27 in-lbs (3Nm).

**This change covers all ranges of regulator, XTX, ATX and TX.**



### **Corrective Action**

Use new torque setting on all service of XTX, ATX and TX second stages. Please make the appropriate corrections for future reference in the following literature:

1. Technical Maintenance Manuals
2. Spare Parts Book

**Should you have any questions regarding this issue,  
please contact our customer service department at:  
(877) 253-DIVE**